

# Facsimile



PLEASE REPORT IF MESSAGE IS NOT CORRECTLY RECEIVED

**DARWIN PORT CORPORATION**  
WHARF OFFICE  
EAST ARM WHARF PORT OPERATIONS – BERRIMAH ROAD - DARWIN

TO:	PORT USERS	FROM:	BEN MIERS ASST.HARBOURMASTER
REF:	NW 2007/07	REF:	DPC2004/384
		FAX NO:	(08) 8947 2373
DATE:	16 <sup>th</sup> February 2007	PHONE NO:	(08) 8947 7203 0401 117 071

---

SUBJECT: NAVIGATION BUOYS LNG1 AND LNG2

Navigation Warning NW2007/06 is cancelled.

Navigation buoys LNG1 and LNG2 have been installed in the following positions:

- LNG1 12°21.165'S 130°43.346'E. Starboard lateral buoy with temporary characteristic Q.G.
- LNG2 12°21.025'S 130°43.544'E. Port lateral buoy with characteristic Iso.R.2s (synchronised).

The navigation buoys LNG 1 and LNG 2 mark a deepwater route for Darwin Port used by LNG vessels.

Navigation buoy 5A has been permanently removed.

Ben Miers.  
Asst. Harbourmaster/Marine Pilot.  
Darwin Port Corporation.

**WARNING:** The information contained in this facsimile message may be confidential information, and may also be the subject of legal privilege, public interest immunity or legal privilege. If you are not the intended recipient, any use, disclosure or copying of this document is unauthorised. If you have received this document in error or part of the transmission fails, please telephone (08) 8922 0660. **Facsimiles on thermal paper can be highly unstable. Important documents should be photocopied before filing/storing.**