

Facsimile



PLEASE REPORT IF MESSAGE IS NOT CORRECTLY RECEIVED

DARWIN PORT CORPORATION
WHARF OFFICE
EAST ARM WHARF PORT OPERATIONS – BERRIMAH ROAD - DARWIN

TO:	PORT USERS	FROM:	BEN MIERS ASST.HARBOURMASTER
REF:	NW 2007/08	REF:	DPC2004/384
		FAX NO:	(08) 8947 2373
DATE:	26 th February 2007	PHONE NO:	(08) 8947 7203 0401 117 071

SUBJECT: LNG1 LIGHT CHARACTERISTIC CHANGED

LNG 1 Navigation Buoy (12°21.165'S 130°43.346'E) has had its flashing characteristic permanently changed to Iso.G.2s (synchronised).

Ben Miers.
Asst. Harbourmaster/Marine Pilot.
Darwin Port Corporation.

WARNING: The information contained in this facsimile message may be confidential information, and may also be the subject of legal privilege, public interest immunity or legal privilege. If you are not the intended recipient, any use, disclosure or copying of this document is unauthorised. If you have received this document in error or part of the transmission fails, please telephone (08) 8922 0660. **Facsimiles on thermal paper can be highly unstable. Important documents should be photocopied before filing/storing.**