

# Facsimile



PLEASE REPORT IF MESSAGE IS NOT CORRECTLY RECEIVED

**DARWIN PORT CORPORATION**  
WHARF OFFICE  
EAST ARM WHARF PORT OPERATIONS – BERRIMAH ROAD - DARWIN

TO:	PORT USERS	FROM:	BEN MIERS ASST.HARBOURMASTER
		REF:	DPC2002/216 <b>NW2006/17</b>
		FAX NO:	(08) 8947 2373
DATE:	31 August 2006	PHONE NO:	(08) 8947 7203 0401 117 071

SUBJECT: CULLEN BAY SHOALING

Shoaling exists in Cullen Bay with a least depth on the 077°T approach leads of 2.2 metres.

Temporary buoys have been placed to indicate the best approach into the Cullen Bay Lock in the following positions:

1. 12° 27.018'S 130° 49.019'E, characteristic QFl.R
2. 12° 27.057'S 130° 49.089'E, characteristic QFl.R
3. 12° 27.098'S 130° 49.088'E, characteristic QFl.G
4. 12° 27.090'S 130° 49.014'E, characteristic QFl.G

A copy of the survey chart indicating the depths in the area can be viewed on the Port of Darwin website at [www.nt.gov.au/dpa/marine\\_notices/marine\\_notices.html](http://www.nt.gov.au/dpa/marine_notices/marine_notices.html).

This notice cancels Australian Notice to Mariners temporary notice 379(T)/2004.

Kind regards,  
Ben Miers.  
Asst. Harbourmaster/Marine Pilot.  
Darwin Port Corporation.

**WARNING:** The information contained in this facsimile message may be confidential information, and may also be the subject of legal privilege, public interest immunity or legal privilege. If you are not the intended recipient, any use, disclosure or copying of this document is unauthorised. If you have received this document in error or part of the transmission fails, please telephone (08) 8922 0660. **Facsimiles on thermal paper can be highly unstable. Important documents should be photocopied before filing/storing.**